Appendix 7 – Photo Log

A photo illustrating the conditions in Jingildy village is illustrated in Figures 1 and 2.

Figure 1. Land use conditions within Jingildy village

Figure 2. Land use conditions within Jingildy village

A photo illustrating the conditions in Kynyr village is illustrated in Figures 3 and 4.

Figure 3. Land use conditions within Kynyr village

Figure 4. Land use conditions within Kynyr village

A photo illustrating the conditions in Muruntov village is illustrated in Figures 5 and 6.

Figure 5. Land use conditions within Muruntov village

Figure 6. Land use conditions within Muruntov village



A photo illustrating the Golden keys resort is illustrated in Figure 7.

Figure 7. Golden Keys resort

A photo illustrating the Gujumli Alviyo holy place is illustrated in Figure 8.

Figure 8. Gujumli Alviyo holy place

A photo illustrating the school in New Tamdy is illustrated in Figure 9.

Figure 9. The school in New Tamdy